

3 metal molding plates (punch, stripper, die)

- ❖ Execute the same machining to 3 plates (punch, stripper, die) and insert knock pins and guide posts. With the condition, examine the machining accuracy.

